

Warranty Multi-Point Vehicle Inspection

Date Monday, May 27, 2024

Vehicle Plate Number DXB AA [REDACTED]

VIN SCBBD6ZH3G [REDACTED]

Mileage 85936KMs

VIN Photo (Max 1 Photos)



Vehicle Make & Model Bentley Mulsanne

Year 2015

Fuel Level 35% - 50%

Vehicle Exterior Photos (Max 4 Photos)





Vehicle Interior Photos (Max 4 Photos)







Engine Oil

	Checked and OKAY	May require attention SOON	Requires IMMEDIATE attention	%	RESET	N/A
Remaining Engine Oil Life	✓			80		

Engine Oil Condition & Service Sticker
(Max 4 Photos)



Exterior Lights

	Checked and OKAY	May require attention SOON	Requires IMMEDIATE attention	OTHER
Headlamps	✓			
Tail Lamps	✓			
R Turn Signal	✓			
L Turn Signal	✓			
Other	✓			

**Battery Test Report & Battery
Terminals (Max 4 Photos)**



Battery

Condition	Checked and OKAY
Cables & Connectors	Checked and OKAY

Battery & Electrical Notes & Parts Requirement

Battery condition is fine

Tread

	3mm or Greater	3mm to 2mm	1.6mm or Less	PSI at	Set to...PSI	Damage Detected	DOT
Left Front		✓		34	40		0121
Right Front		✓		33	40		0123
Left Rear		✓		35	42		0921
Right Rear		✓		33	42		0122

Tyre & Wheel Damages (Max 8 Photos)







Services

Rotation Needed	No
-----------------	----

Alignment Needed	No
Balance Needed	No

Tyre & Wheels Notes & Parts Requirement

Rims has scratches need to replace

Rear right rim is bend

FRONT - Check / Measure Front & Rear Brake Lining

	Minimum Thickness	Actual Thickness	Uneven Surface
Left Front Brake Pad	4mm	10mm	
Left Front Brake Disc	36mm	33.8mm	
Right Front Brake Pad	4mm	10mm	
Right Front Brake Disc	36mm	33.8mm	

REAR - Check / Measure Front & Rear Brake Lining

	Minimum Thickness	Actual Thickness	Uneven Surface
Left Rear Brake Pad	4mm	8mm	
Left Rear Brake Disc	28mm	28.5mm	
Right Rear Brake Pad	4mm	8mm	
Right Rear Brake Disc	28mm	28.5mm	

Brake System

Lines	Checked and OKAY
Hoses	Checked and OKAY
Parking Brake	Checked and OKAY
Brake Actuation	Checked and OKAY

Front & Rear Brake Pad + Disc
Condition (Max 8 Photos)









Brake System Notes & Parts Requirement

Front brake discs is below minimum thickness - need to replace

Rear brake discs is approaching minimum thickness

Brake pads are new

Blades

Left Front	Checked and OKAY
Right Front	Checked and OKAY
Rear (if applicable)	Checked and OKAY
Windshield Condition	Checked and OKAY
Windshield Cracks	Checked and OKAY
Windshield Chips	Checked and OKAY

Wiper Blade Condition & Windshield Chips/Cracks (Max 4 Photos)





Windshield System Notes & Parts Requirement

Wiper blade condition is fine

Levels

Engine Oil	Okay
Brake Fluid Reservoir	Requires IMMEDIATE Attention
Transmission (if equipped w/dipstick)	Requires IMMEDIATE Attention
Coolant Reservoir	Okay
Power Steering	Requires IMMEDIATE Attention
Windshield Washer	Topped Up

Fluid Level Photos & Condition (Max 4 Photos)





Fluid System Notes & Parts Requirement

Transmission oil service is required

Power steering oil is required

Rear differential oil need to change

A/C System

A/C Air Flow	May require attention SOON
A/C Cooling IDLE	Checked and OKAY
A/C Cooling DRIVING	Checked and OKAY
A/C Vent Condition	Checked and OKAY
A/C Smell	Checked and OKAY
A/C Comprehensive Check	Checked and OKAY

A/C System Faults & Condition (Max 4 Photos)







A/C System Notes & Parts Requirement

AC cooling is good

Cabin air filter need to replace. It is blocked

Suspension System

Shock Absorber, Springs & Mounts	Requires IMMEDIATE attention
Control Arms, Sway Bar & Link Rods	Requires IMMEDIATE attention
Bushes & Bearings	May require attention SOON
Ball Joints	Requires IMMEDIATE attention

Suspension System Faults & Condition (Max 8 Photos)











Suspension Notes & Parts Requirement

Rear shock absorbers is worn out - need to replace
Front lower arms assembly replace - bushes are cracked
Front upper arm assembly replace - bushes are cut
Front lower arms balljoints are defective both side

Powertrain System

Engine, Transmission, Drive Axle, Transfer Cases	Checked and OKAY
Belts: Engine, Accessory, Serpentine, and / or V-drive	Requires IMMEDIATE attention
Engine Cooling System & Hoses	Checked and OKAY
Engine Air Filter & Housing	Requires IMMEDIATE attention
Exhaust System Components	Checked and OKAY

Powertrain System Faults & Condition
(Max 8 Photos)







Powertrain System Notes & Parts Requirement

Engine air filter need to replace
Engine drive belt need to replace
Drive belt tensioner and idle pulley need to replace

Paint & Body Faults & Condition (Max 16 Photos)













Paint & Body Notes & Parts Requirement

FR door paint is required > door handle side and mirror side is peeling
 Right side under chassis has been repaired and painted

Inspect for Visible Leaks and Visual Condition

Fuel System (includes gas cap seating)	Checked and OKAY
Hoses: Power Steering and HVAC	Checked and OKAY
Cabin Air Filter	Requires IMMEDIATE attention
Passenger Compartment Air Filter	Checked and OKAY
Steering Components and Steering Linkage	Requires IMMEDIATE attention
CV Drive Axle Boots or Driveshafts and U-joints	Checked and OKAY
Check Engine Light	Checked and OKAY
Body Components Lubrication	Checked and OKAY
Restraint System Component Check	Checked and OKAY
Chassis Components Lubrication	Checked and OKAY
Drive Axle (Leak / Other)	May require attention SOON
Radio & Infotainment System	Checked and OKAY

**Additional Checks Faults & Condition
(Max 8 Photos)**





Notes & Parts Requirement

Body
F.R door handle and side mirror painting required

NOTE:
FR under chassis repair has been detected

Engine
Engine drive belt
Engine air filter
Drive belt tensioner and idle pulleys
No service sticker found. Recommended to do service.
Cabin air filter
Transmission oil and filter
Rear differential seal
Rear differential oil

Under chassis
Front lower arms assembly
Front balljoint
Steering rack assembly
Steering coupling - has play
Front upper arm assembly 2pcs
Rear shock absorbers

Please refer the OBD scan report for electrical faults.

Signature

A handwritten signature in black ink, consisting of a stylized 'H' followed by a large, loopy 'S' and a horizontal line.